





Page N°: 1/2

Hai Phong City, Date: 12 April 2021

REF. NO.: 254872.2 Q1

## **CERTIFICATE OF QUALITY**

A shipment designated as:

BY: SHIPPER:

NOTIFY ADDRESS:

COMMODITY AS B/L: QUANTITY AS B/L:

PORT OF LOADING:

PORT OF DISCHARGE: NAME OF VESSEL:

B/L NO .:

SLAG IN BULK

12,895.00 M.TONS

CAM PHA PORT, VIETNAM CHATTOGRAM, BANGLADESH

MV. EVER PRECIOUS

DSSL-08/2021/B1

DATED: 10TH APR, 2021

THIS IS TO REPORT THAT, in compliance with the instructions received from our principal, I / LIMITED, we attended at CAM PHA PORT, VIETNAM with the purpose of carrying out survey of sampling and analysis of the above mentioned commodity. At time of our intervention, the cargo in bulk was being loaded on board the vessel at CAM PHA PORT, VIETNAM. We hereby report our findings as follows:

SAMPLING AND ANALYSIS: As the client's instruction, increment sample has been drawn randomly from barges for 02 lots of total quantity @22,205 tons slag in bulk during loading onto the vessel at CAM PHA PORT, VIETNAM. The sample of each lot were reduced, sealed and sent to lab then prepared into parts with one part was kept for whole shipment preparation. Representative sample for whole shipment was then prepared into 05 full composite (F.C) samples and distributed as follows:

- 01 F.C sample with SGS seal no. Q3136183 was sent to lab for further preparation and testing.
- 01 F.C sample with SGS seal no. Q3136181 was retained at SGS office and will be disposed after 03
- 02 F.C samples with SGS seals no. Q3136185 & Q3136184 were handed over to the client's representative.
- 01 F.C sample with SGS seal no. Q3136182 was handed over to the vessel's representative.




## SGS Vietnam Ltd.

198 Nguyen Thi Minh Khai Street Ward 6, District 3. Ho Chi Minh City - Vietnam t + 84 28 3935 1920 f: +84 28 3935 1921

This document is issued by the Company subject to its General Conditions of Service ). Attention is drawn to the limitations of liability, indemnification and jurisdictional issues established therein.

indemnification and jurisdictional issues established therein. This document is to be treated as an original within the meaning of UCP 600. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

The authenticity of this document may be verified at https://sgsonsite.sgs.com/en/v2/common/ecertificate/authenticateeCertificate.jsp.







Page N°: 2/2

The testing results of total quantity @22,205 tons as report no. HPM21-13190 R0 were applied to this partial shipment as the client's instruction as follows:

Specification	Unit	Testing results		Testing methods
CaO	%	48.35	(Four eight decimal three five)	
MgO	%	2.42	(Two decimal four two)	EN 196-2:2013
Al <sub>2</sub> O <sub>3</sub>	%	3.02	(Three decimal zero two)	
FeO	%	0.19	(Zero decimal one nine)	ASTM D3872-19
SiO <sub>2</sub>	%	39.67	(Three nine decimal six seven)	EN 196-2:2013
Moisture (Average)	%	9.82	(Nine decimal eight two)	EN 15167-1:2006

Remarks:

During loading, apart of slag on barges VP2199, VP1576, BN1486, HD2081 was found to be in lumps with big size, even over 300mm and very hard. However, as the client's instruction, such cargo was still loaded into the vessel's holds without any separation and removals.

Survey was carried out at CAM PHA PORT, VIETNAM & SGS's lab from 04 to 12 April 2021.





## SGS Vietnam Ltd.

198 Nguyen Thi Minh Khai Street Ward 6, District 3. Ho Chi Minh City - Vietnam t + 84 28 3935 1920 f: +84 28 3935 1921

This document is issued by the Company subject to its General Conditions of Service (<a href="https://www.sgs.com/en/Terms-and-Conditions.aspx">www.sgs.com/en/Terms-and-Conditions.aspx</a>). Attention is drawn to the limitations of liability,

(www.sos.com/en/Terms-and-Conditions, aspx). Attention is drawn to the limitations of liability, indemnification and jurisdictional issues established therein.

This document is to be treated as an original within the meaning of UCP 600. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

The authenticity of this document may be verified at

The authenticity of this document may be verified at https://sgsonsite.sgs.com/en/v2/common/ecertificate/authenticatee Certificate.jsp